

# Appendix B. Setup Photographs

# <Conducted Emission>

### Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : B1 of B2
Report Issued Date : Oct. 10, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR683002A




Report No.: FR683002A


# <Radiated Emission>

## **Z** Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : B2 of B2
Report Issued Date : Oct. 10, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1