

Appendix D. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number D1 of D2
Report Issued Date Oct. 10, 2016
Report Version : Rev. 01


Report No.: FR683002C

Report Template No.: BU5-FR15CWL Version 1.3


<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number D2 of D2
Report Issued Date Oct. 10, 2016
Report Version : Rev. 01

Report No.: FR683002C

Report Template No.: BU5-FR15CWL Version 1.3