

Appendix D. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : D1 of D2
Report Issued Date : Oct. 10, 2016
Report Version : Rev 01

Report No.: FR683002B


Report Template No.: BU5-FR15CBT4.0 Version 1.3




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : D2 of D2
Report Issued Date : Oct. 10, 2016
Report Version : Rev 01

Report No.: FR683002B

Report Template No.: BU5-FR15CBT4.0 Version 1.3