

### Appendix C. Setup Photographs

# <Conducted Emission> Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : C1 of C3
Report Issued Date : May 03, 2016
Report Version : Rev. 01

Report No.: FR630205F


Report Template No.: BU5-FR15EWLB4 AC MA Version 1.3




#### <Radiated Emission>

#### Z Plane for WLAN5GHz 802.11a

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : C2 of C3
Report Issued Date : May 03, 2016
Report Version : Rev. 01


Report No.: FR630205F

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.3


FCC Test Report No.: FR630205F

## Y Plane for WLAN5GHz 802.11n HT20/HT40/WLAN5GHz 802.11ac VHT20/VHT40/VHT80

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : C3 of C3
Report Issued Date : May 03, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.3