
Appendix C. Setup Photographs

<Radiated Emission>

Top Antenna

X Plane for 22H

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : C1 of C6
Report Issued Date : Oct. 10, 2016
Report Version : Rev. 01

Report No.: FG683002A

Report No.: FG683002A

Y Plane for 24E

LF



HF




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : C2 of C6
Report Issued Date : Oct. 10, 2016
Report Version : Rev. 01


CRF Test Report No. : FG683002A

Y Plane for 27L

LF



HF




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : C3 of C6
Report Issued Date : Oct. 10, 2016
Report Version : Rev. 01

Bottom Antenna

Z Plane for 22H

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : C4 of C6
Report Issued Date : Oct. 10, 2016
Report Version : Rev. 01

Report No.: FG683002A


Report No.: FG683002A

Y Plane for 24E

LF



HF




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : C5 of C6
Report Issued Date : Oct. 10, 2016
Report Version : Rev. 01

Report No.: FG683002A

Y Plane for 27L

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : C6 of C6
Report Issued Date : Oct. 10, 2016
Report Version : Rev. 01