## 1. External Photograph of EUT

Brand Name: LeEco; Model Name: LEX727

Report No.: EP683002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : 1 of 35
Report Issued Date : Oct. 10, 2016






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : 2 of 35
Report Issued Date : Oct. 10, 2016
Report Version : Rev. 01

Report No.: EP683002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : 3 of 35 Report Issued Date : Oct. 10, 2016

Report No.: EP683002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : 4 of 35 Report Issued Date : Oct. 10, 2016


Report No.: EP683002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : 5 of 35
Report Issued Date : Oct. 10, 2016

Duand Names LaCase Madel Names LEV707

Report No.: EP683002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : 6 of 35 Report Issued Date : Oct. 10, 2016

: Rev. 01

Report Version

## 2. Photograph of Accessory

Brand Name: LeEco; Model Name: LEX727

Report No.: EP683002

## **List of Accessory:**


Specification of Accessory		
IAC Adantor	Brand Name	LeEco
	Model Name	EQ-24BUS
IRattory	Brand Name	LeEco
	Model Name	LTF23A
USB Cable	Signal Line Type	1.05m, shielded cable, without core
Earphone	Signal Line Type	1.20m, non-shielded cable, without core

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : 7 of 35
Report Issued Date : Oct. 10, 2016

Report No.: EP683002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : 8 of 35
Report Issued Date : Oct. 10, 2016
Report Version : Rev. 01


Report No.: EP683002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : 9 of 35
Report Issued Date : Oct. 10, 2016



Report No.: EP683002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727

: 10 of 35 Page Number Report Issued Date : Oct. 10, 2016 Report Version : Rev. 01



Report No.: EP683002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727

Page Number : 11 of 35 Report Issued Date : Oct. 10, 2016