

Appendix B. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : B1 of B2
Report Issued Date : May 03, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1


Report No.: FR630205A




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : B2 of B2
Report Issued Date : May 03, 2016
Report Version : Rev. 01

Report No.: FR630205A

Report Template No.: BU5-FR15CBT Version 1.1