Appendix C. Setup Photographs

<Radiated Emission>

Z Plane for 22H

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : C1 of C3
Report Issued Date : May 03, 2016
Report Version : Rev. 01

Report No.: FG630205A

Report Template No.: BU5-FG22/24/27 Version 1.1

X Plane for 24E

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : C2 of C3
Report Issued Date : May 03, 2016
Report Version : Rev. 01

Report No. : FG630205A


Report Template No.: BU5-FG22/24/27 Version 1.1

Y Plane for 27L

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : C3 of C3
Report Issued Date : May 03, 2016
Report Version : Rev. 01

Report No. : FG630205A

Report Template No.: BU5-FG22/24/27 Version 1.1