Test report No.
 : 10767588H-B

 Page
 : 32 of 34

 Issued date
 : November 17, 2015

 FCC ID
 : 2AFXHN1C05B

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 10767588H-B
Page : 33 of 34
Issued date : November 17, 2015
FCC ID : 2AFXHN1C05B

Radiated Spurious Emission



Photo 1



Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 10767588H-B

 Page
 : 34 of 34

 Issued date
 : November 17, 2015

 FCC ID
 : 2AFXHN1C05B

Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis)

X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124