

Appendix E. Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZUSAP102 Page Number : E1 of E4
Report Issued Date : Jul. 14, 2016
Report Version : Rev. 01

Report No.: FR652049E





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZUSAP102 Page Number : E2 of E4
Report Issued Date : Jul. 14, 2016
Report Version : Rev. 01

Report No.: FR652049E



Report No.: FR652049E


<Radiated Emission>

X Plane for Non-TXBF Modes

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZUSAP102

: E3 of E4 Page Number Report Issued Date: Jul. 14, 2016 Report Version : Rev. 01




Report No. : FR652049E

X Plane for TXBF Modes

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZUSAP102 Page Number : E4 of E4
Report Issued Date : Jul. 14, 2016
Report Version : Rev. 01