Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF6LG Page Number : D1 of D2
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR8D1803A


<Radiated Emission>

Y Plane

LF







——THE END—

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF6LG Page Number : D2 of D2
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR8D1803A