Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF10G Page Number : E1 of E2
Report Issued Date Apr. 25, 2019
Report Version : Rev. 01
Report Template No.: BU5-FR15CBLE Version 2.0

Report No.: FR931204B


<Radiated Emission> (Bluetooth v4.0/5.0 LE)

X Plane

LF







Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF10G Page Number : E2 of E2
Report Issued Date Apr. 25, 2019
Report Version : Rev. 01

Report No.: FR931204B

Report Template No.: BU5-FR15CBLE Version 2.0