

Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : D1 of D2
Report Issued Date : Mar. 14, 2019
Report Version : Rev. 01


Report No.: FR911620D

Report Template No.: BU5-FR15CNFC Version 2.0




Report No.: FR911620D

<Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : D2 of D2
Report Issued Date : Mar. 14, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0