


Appendix D. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSC3CG Page Number : D1 of D2
Report Issued Date Jun. 12, 2018
Report Version : Rev. 01

Report No.: FR841616-01A

Report Template No.: BU5-FR15CBT Version 2.0




Report No.: FR841616-01A


<Radiated Emission>

Z Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSC3CG Page Number : D2 of D2
Report Issued Date Jun. 12, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0