
## Appendix C. Setup Photographs


<Radiated Emission>

X Plane for 22H

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RSG138 Page Number : C1 of C2
Report Issued Date : Feb. 13, 2017
Report Version : Rev. 01

Report No. : FG6D1401A


Report Template No.: BU5-FG22/24 Version 1.2

## Y Plane for 24E

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RSG138 Page Number : C2 of C2
Report Issued Date : Feb. 13, 2017
Report Version : Rev. 01

Report No.: FG6D1401A

Report Template No.: BU5-FG22/24 Version 1.2