

# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 1



Mode 6



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RSG138 Page Number : A1 of A2
Report Issued Date : Feb. 13, 2017
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3

Report No. :FC6D1401


# <Radiated Emission>

## Mode 6

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RSG138 Page Number : A2 of A2
Report Issued Date : Feb. 13, 2017
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3