

Appendix D. Setup Photographs

<Conducted Emission>

Mode 2



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6G Page Number : D1 of D2
Report Issued Date Apr. 04, 2018
Report Version : Rev. 01

Report No.: FR820819B


Report Template No.: BU5-FR15CBT4.0 Version 2.0




<Radiated Emission>

Z Plane

LF





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6G Page Number : D2 of D2
Report Issued Date Apr. 04, 2018
Report Version : Rev. 01

Report No.: FR820819B

Report Template No.: BU5-FR15CBT4.0 Version 2.0