# Appendix C. Setup Photographs


### <Radiated Emission>

X Plane for LTE Band 2

LF




HF




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : C1 of C5
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

## Y Plane for LTE Band 4/38

LF



HF



Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : C2 of C5
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

## Z Plane for LTE Band 5/7/12

LF



HF




Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : C3 of C5
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

## Y Plane for LTE Band 7CA

LF



HF




Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : C4 of C5
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

## Z Plane for LTE Band 38CA

LF



HF



———THE END———

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : C5 of C5
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0