

## Report No.: FR842002A

# Appendix D. Setup Photographs

### <Conducted Emission>

#### Mode 1





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZZ-XME1A Page Number : D1 of D2 : Jun. 11, 2018 Report Issued Date Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 2.0




#### <Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZZ-XME1A Page Number : D2 of D2
Report Issued Date : Jun. 11, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR842002A