
Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for LTE Band 2

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSC3CG Page Number : C1 of C4 Report Issued Date : Jun. 12, 2018 Report Version : Rev. 01

Report No.: FG841616-01B


Report Template No.: BU5-FGLTE Version 2.0

Z Plane for LTE Band 4/5

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSC3CG Page Number : C2 of C4
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01

Report No. : FG841616-01B


Report Template No.: BU5-FGLTE Version 2.0

Z Plane for LTE Band 7

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSC3CG Page Number : C3 of C4
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0


Report No. : FG841616-01B

Z Plane for LTE Band 38

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSC3CG Page Number : C4 of C4
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01

Report No. : FG841616-01B

Report Template No.: BU5-FGLTE Version 2.0