


Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : E1 of E2
Report Issued Date Aug. 02, 2018
Report Version : Rev. 01

Report No.: FR862604C


Report Template No.: BU5-FR15CWL AC MA Version 2.0



<Radiated Emission>

Z Plane

LF







Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : E2 of E2
Report Issued Date Aug. 02, 2018
Report Version : Rev. 01

Report No.: FR862604C

Report Template No.: BU5-FR15CWL AC MA Version 2.0