
Appendix E. Setup Photographs

<Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF10G Page Number : E1 of E2
Report Issued Date Apr. 25, 2019
Report Version : Rev. 01


Report No.: FR931204C

Report Template No.: BU5-FR15CWL AC MA Version 2.0


<Radiated Emission>

Y Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF10G Page Number : E2 of E2
Report Issued Date Apr. 25, 2019
Report Version : Rev. 01

Report No.: FR931204C

Report Template No.: BU5-FR15CWL AC MA Version 2.0