

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSD1SG Page Number : D1 of D2
Report Issued Date May 16, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR840407A



<Radiated Emission>

X Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSD1SG Page Number : D2 of D2
Report Issued Date May 16, 2018
Report Version : Rev. 01

Report No.: FR840407A

Report Template No.: BU5-FR15CBT Version 2.0