

Appendix B. Setup Photographs

<Conducted Emission>





Sporton International (KunShan) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : B1 of B2
Report Issued Date Jul. 12, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR762302A






<Radiated Emission>
Y Plane
LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : B2 of B2
Report Issued Date Jul. 12, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR762302A