Appendix C. Setup Photographs


<Radiated Emission>

X Plane for LTE Band 5

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSC3DG Page Number : C1 of C3
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6


Report No.: FG841618-01B

Y Plane for LTE Band 7

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSC3DG Page Number : C2 of C3
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6


Report No. : FG841618-01B

Y Plane for LTE Band 2/4/38

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSC3DG Page Number : C3 of C3
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6

Report No. : FG841618-01B