

Report No.: FR842002B

Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZZ-XME1A Page Number : E1 of E2 Report Issued Date : Jun. 11, 2018 Report Version : Rev. 01


Report Template No.: BU5-FR15CBT4.0/5.0 Version 2.0




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZZ-XME1A Page Number : E2 of E2
Report Issued Date : Jun. 11, 2018
Report Version : Rev. 01

Report No.: FR842002B

Report Template No.: BU5-FR15CBT4.0/5.0 Version 2.0