

Appendix E. Setup Photographs

<Conducted Emission>

Mode 1



Remote View



Rear View

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : E1 of E2
Report Issued Date : Mar. 19, 2019
Report Version : Rev. 01


Report No.: FR911620F

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.4




<Radiated Emission>

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX:86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : E2 of E2
Report Issued Date : Mar. 19, 2019
Report Version : Rev. 01

Report No.: FR911620F

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.4