Appendix D. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF2G Page Number : D1 of D2
Report Issued Date Feb. 25, 2019
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0


Report No.: FR8D2708A

Report No.: FR8D2708A

<Radiated Emission>

X Plane

LF







TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF2G Page Number : D2 of D2
Report Issued Date Feb. 25, 2019
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0