Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : E1 of E3
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01


Report No.: FR882808B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0

<Radiated Emission>

X Plane for Bluetooth LE v4.2

LF



HF



Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : E2 of E3
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01

Report No.: FR882808B


Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0

Y Plane for Bluetooth LE v5.0

LF



HF



——THE END——

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : E3 of E3
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01

Report No.: FR882808B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0