


Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID:: 2AFZZ-XMSE10A Page Number : D1 of D2
Report Issued Date : Jun. 20, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR850814A




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID:: 2AFZZ-XMSE10A Page Number : D2 of D2
Report Issued Date : Jun. 20, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR850814A