



Report No.: FR931204-03D

Appendix B. Setup Photographs

<Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF10G Page Number : D1 of D1
Report Issued Date : Jun. 24, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0