
## Appendix C. Setup Photographs


## <Radiated Emission>

Y Plane for Band 2 / 4 / 7 / 38\_CA

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSF10G Page Number : C1 of C3
Report Issued Date : Apr. 25, 2019
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0

Report No.: FG931204B

## Z Plane for Band 5 / 38

LF



HF




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSF10G Page Number : C2 of C3
Report Issued Date : Apr. 25, 2019
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0

Report No.: FG931204B

## Z Plane for Band 7C\_CA

LF



HF



——THE END——

Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSF10G Page Number : C3 of C3
Report Issued Date : Apr. 25, 2019
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0

Report No.: FG931204B