

Report No.: FR840407D

## Appendix E. Setup Photographs

## <Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSD1SG

: E1 of E2 Page Number Report Issued Date : May 16, 2018 : Rev. 01 Report Version

Report Template No.: BU5-FR15EWL AC MA Version 2.0



Report No.: FR840407D


## <Radiated Emission>

X Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSD1SG Page Number : E2 of E2
Report Issued Date : May 16, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC MA Version 2.0