

Report No.: FR762302B

Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6

Page Number : D1 of D2 Report Issued Date : Jul. 12, 2017 Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.2 Version 2.0




<Radiated Emission>

Z Plane

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : D2 of D2 Report Issued Date : Jul. 12, 2017

Report No.: FR762302B

Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.2 Version 2.0