Appendix C. Setup Photographs

<Radiated Emission>

Y Plane for Band 2 / 7 / 38 / 7_CA / 38_CA

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSF11G Page Number : C1 of C3
Report Issued Date : Jul. 08, 2019
Report Version : Rev. 01


Report No.: FG921903-02B

Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG921903-02B

Z Plane for Band 4

LF



HF




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSF11G Page Number : C2 of C3
Report Issued Date : Jul. 08, 2019
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG921903-02B

Z Plane for Band 5

LF



HF



——THE END——

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSF11G Page Number : C3 of C3
Report Issued Date : Jul. 08, 2019
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0