

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 59 of 84
Report Issued Date : Jan. 23, 2019

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 60 of 84
Report Issued Date : Jan. 23, 2019

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 61 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 62 of 84
Report Issued Date : Jan. 23, 2019


Report No.: EP8O2308-01



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H


: 63 of 84 Page Number Report Issued Date : Jan. 23, 2019

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 64 of 84
Report Issued Date : Jan. 23, 2019

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 65 of 84
Report Issued Date : Jan. 23, 2019

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 66 of 84 Report Issued Date : Jan. 23, 2019

Report No.: EP8O2308-01



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 67 of 84
Report Issued Date : Jan. 23, 2019


Report No.: EP8O2308-01



Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 68 of 84
Report Issued Date : Jan. 23, 2019

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 69 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 70 of 84
Report Issued Date : Jan. 23, 2019

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 71 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 72 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 73 of 84
Report Issued Date : Jan. 23, 2019

Report No.: EP8O2308-01



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 74 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 75 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 76 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 77 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 78 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 79 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 80 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01


Report No.: EP8O2308-01

Brand Name: Redmi; Model Name: M1901F7H **7 Antenna position** WWAN Diversity Antenna < Rx> **Bluetooth & W GNSS Antenna** INC. 007225040024740 STA STA SE OF 02 02 02 07 08 02 001 or os os 04 02 09 07 08 02 000 or

Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 81 of 84
Report Issued Date : Jan. 23, 2019

Report No.: EP8O2308-01




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 82 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 83 of 84
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: EP8O2308-01



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7H Page Number : 84 of 84
Report Issued Date : Jan. 23, 2019