
Appendix C. Setup Photographs


<Radiated Emission>

X Plane for GSM/WCDMA Band V

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : C1 of C4
Report Issued Date : Mar. 15, 2019
Report Version : Rev. 01


Report No.: FG911620A

Z Plane for GSM/WCDMA Band II

LF



HF




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : C2 of C4
Report Issued Date : Mar. 15, 2019
Report Version : Rev. 01

Report No.: FG911620A

Report No. : FG911620A

X Plane for WCDMA Band IV

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : C3 of C4
Report Issued Date : Mar. 15, 2019
Report Version : Rev. 01

Z Plane for CDMA BC0

LF



HF



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : C4 of C4
Report Issued Date : Mar. 15, 2019
Report Version : Rev. 01

Report No. : FG911620A