Appendix E. Setup Photographs

<Conducted Emission>

Mode 1



Report No.: FR931204E

Remote View



Rear View


Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX:86-512-57900958 FCC ID: 2AFZZ-XMSF10G Page Number : E1 of E2
Report Issued Date : Apr. 25, 2019
Report Version : Rev. 01


Report Template No.: BU5-FR15EWL AC MA Version 2.0

<Radiated Emission>

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF10G Page Number : E2 of E2
Report Issued Date : Apr. 25, 2019
Report Version : Rev. 01

Report No.: FR931204E

Report Template No.: BU5-FR15EWL AC MA Version 2.0