

Appendix E. Setup Photographs

<Conducted Emission>

Mode 1



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSD1SG Page Number : E1 of E2
Report Issued Date May 16, 2018
Report Version : Rev. 01

Report No.: FR840407B

Report Template No.: BU5-FR15CBT4.0 Version 2.0




<Radiated Emission>

X Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSD1SG Page Number : E2 of E2
Report Issued Date May 16, 2018
Report Version : Rev. 01

Report No.: FR840407B

Report Template No.: BU5-FR15CBT4.0 Version 2.0