

## Appendix D. Setup Photographs

## <Conducted Emission>





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZZ-XME1A Page Number : D1 of D2
Report Issued Date : Jun. 11, 2018
Report Version : Rev. 01


Report No.: FR842002D

Report Template No.: BU5-FR15CNFC Version 2.0




## Report No.: FR842002D

## <Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZZ-XME1A Page Number : D2 of D2
Report Issued Date : Jun. 11, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0