

# Appendix E. Setup Photographs

## <Conducted Emission>

#### Mode 1



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF6LG Page Number : E1 of E2
Report Issued Date Jan. 23, 2019
Report Version : Rev. 01

Report No.: FR8D1803C

Report Template No.: BU5-FR15CWL AC MA Version 2.0




## Report No. : FR8D1803C


### <Radiated Emission>

#### **Z** Plane

LF



HF



———THE END——

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF6LG Page Number : E2 of E2
Report Issued Date Jan. 23, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL AC MA Version 2.0