
## Appendix E. Setup Photographs

## <Conducted Emission>

## Mode 1



Remote View



Rear View

Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : E1 of E2
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01

Report No.: FR8N2303E


Report Template No.: BU5-FR15EWL AC MA Version 2.0

## <Radiated Emission>

LF



HF



——THE END—

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : E2 of E2
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01

Report No.: FR8N2303E

Report Template No.: BU5-FR15EWL AC MA Version 2.0