Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF2G Page Number : E1 of E2
Report Issued Date Feb. 25, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CWLAN Version 2.0


Report No.: FR8D2708C

Report No.: FR8D2708C


<Radiated Emission>

X Plane

LF







TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF2G Page Number : E2 of E2
Report Issued Date Feb. 25, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CWLAN Version 2.0