

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RSG138 Page Number : D1 of D2
Report Issued Date : Feb. 13, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.1 Version 1.3

Report No.: FR6D1401B




Report No. : FR6D1401B


<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RSG138 Page Number : D2 of D2
Report Issued Date : Feb. 13, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.1 Version 1.3