Appendix A. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSD5X Page Number : A1 of A4
Report Issued Date : Apr. 08, 2018
Report Version : Rev. 01

Report No.: FC820821

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC820821

Mode 8





Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSD5X Page Number : A2 of A4
Report Issued Date : Apr. 08, 2018
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 6

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AFZZ-XMSD5X Page Number : A3 of A4
Report Issued Date : Apr. 08, 2018
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3

Report No.: FC820821


Report No.: FC820821

Mode 7

LF



H



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSD5X Page Number : A4 of A4
Report Issued Date : Apr. 08, 2018
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3