

Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : D1 of D2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0


Report No.: FR762302C



<Radiated Emission>

Z Plane

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : D2 of D2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0

Report No.: FR762302C