
Appendix C. Setup Photographs


<Radiated Emission>

Z Plane for 22H

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSD2SG Page Number : C1 of C3
Report Issued Date : Jun. 14, 2018
Report Version : Rev. 01
Report Template No.: BU5-FG22/24/27 Version 2.0

Report No.: FG842008A


Report No.: FG842008A

Y Plane for 24E

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSD2SG Page Number : C2 of C3
Report Issued Date : Jun. 14, 2018
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 2.0


Report No.: FG842008A

Y Plane for 27L

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSD2SG Page Number : C3 of C3
Report Issued Date : Jun. 14, 2018
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 2.0