
## Appendix C. Setup Photographs


<Radiated Emission>

Z Plane for LTE Band 4

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSD5X Page Number : C1 of C4
Report Issued Date : Apr. 08, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6


Report No.: FG820821B

## Y Plane for LTE Band 7

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSD5X Page Number : C2 of C4
Report Issued Date : Apr. 08, 2018

Report No. : FG820821B


Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6

## Y Plane for LTE Band 12/13/26/41

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSD5X Page Number : C3 of C4
Report Issued Date : Apr. 08, 2018
Report Version : Rev. 01

Report No. : FG820821B


Report Template No.: BU5-FGLTE Version 1.6

## Y Plane for LTE Band 25

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSD5X Page Number : C4 of C4
Report Issued Date : Apr. 08, 2018
Report Version : Rev. 01

Report No. : FG820821B

Report Template No.: BU5-FGLTE Version 1.6