Appendix A. Setup Photographs

<Conducted Emission>

Mode 2





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSF9SH Page Number : A1 of A2
Report Issued Date : Jun. 25, 2019
Report Version : Rev. 01


Report No.: FC941708-01

Report Template No.: BU5-FD15B Version 3.0


<Radiated Emission>

Mode 5

LF



HF



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XMSF9SH Page Number : A2 of A2
Report Issued Date : Jun. 25, 2019
Report Version : Rev. 01
Report Template No.: BU5-FD15B Version 3.0

Report No.: FC941708-01