

# Appendix B. Setup Photographs

## <Conducted Emission>

#### Mode 2



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6G Page Number : B1 of B2
Report Issued Date Apr. 04, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR820819A




### <Radiated Emission>

#### **Z** Plane

LF





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6G Page Number : B2 of B2
Report Issued Date Apr. 04, 2018
Report Version : Rev. 01

Report No.: FR820819A

Report Template No.: BU5-FR15CBT Version 2.0